

146(T)/2016 VIET NAM - NORTH EAST COAST - HAI PHONG - Buoyage.

Source: Viet Nam Maritime Safety - North Notice No. 232/TBHH-TCTBĐATHH MB

Chart affected - VN50007 (Edition number 1, Edition date April 16th, 2015)

The following lateral buoys and special buoy are temporarily out of service:

<i>Designation</i>	<i>Characteristic</i>	<i>Position</i>
HP11	Fl.G.3s	20°45.67'N 106°56.38'E
HP13	Fl.G.3s	20°46.37'N 106°55.84'E
HP15B	Fl(3+1)Y.12s	20°48.32'N 106°54.81'E

(All positions are referred to WGS84 Datum)

146(T)/2016 VIỆT NAM - BỜ BIỂN ĐÔNG BẮC BỘ - HẢI PHÒNG - Phao.

Nguồn: Tổng công ty Bảo đảm an toàn hàng hải miền Bắc, Thông báo số 232/TBHH-TCTBĐATHH MB

Hải đồ ảnh hưởng - VN50007 (Phiên bản 1, ngày 16 tháng 4 năm 2015)

Các phao luồng và phao đặc biệt sau đây tạm ngừng hoạt động:

<i>Tên</i>	<i>Đặc tính</i>	<i>Vị trí</i>
HP11	Fl.G.3s	20°45.67'N 106°56.38'E
HP13	Fl.G.3s	20°46.37'N 106°55.84'E
HP15B	Fl(3+1)Y.12s	20°48.32'N 106°54.81'E

(Tất cả các vị trí được tham chiếu theo hệ tọa độ WGS84)