

**125(T)/2017 VIET NAM - NORTH CENTRAL COAST - THANH HOA - NGHI SON - Buoyage.**

Source: Viet Nam Maritime Safety - North Notice No.181/TBHH-TCTBĐATHH MB

**Chart affected - VN50012 (Edition number 2, Edition date Apr 11<sup>th</sup>, 2017)**

Lateral buoy, *Mo(A)6s*, in position 19°16.63'N, 105°50.65'E is temporarily out of service.

Lateral buoy, *Fl.G.3s*, in position 19°17.22'N, 105°50.07'E is temporarily out of service.

(All positions are referred to WGS84 Datum)

**125(T)/2017 VIỆT NAM - BỜ BIỂN BẮC TRUNG BỘ - THANH HÓA - NGHI SƠN - Hệ thống phao.**

Nguồn: Tổng công ty Bảo đảm an toàn hàng hải miền Bắc, Thông báo số 181/TBHH-TCTBĐATHH MB

**Hải đồ ảnh hưởng - VN50012 (Phiên bản 2, ngày 11 tháng 4 năm 2017)**

Phao luồng, *Mo(A)6s*, ở vị trí 19°16.63'N, 105°50.65'E tạm ngừng hoạt động.

Phao luồng, *Fl.G.3s*, ở vị trí 19°17.22'N, 105°50.07'E tạm ngừng hoạt động.

(Tất cả các vị trí được tham chiếu theo hệ tọa độ WGS84)