

259(T)/2018 VIET NAM - SOUTH CENTRAL COAST - QUANG NGAI - DUNG QUAT -Buoyage.

Source: Viet Nam Maritime Safety - North Notice No.380(T)/2018/TBHH-TCTBĐATHH MB

Lateral buoy, *Fl.G.3s*, in position 15°24.27'N, 108°47.56'E is temporarily out of service.

Lateral buoy, *Fl.G.3s*, in position 15°23.90'N, 108°47.57'E is temporarily out of service.

East Cardinal Buoy, *Q(3)10s*, in position 15°23.73'N, 108°47.44'E is temporarily out of service.

(All positions are referred to WGS84 Datum)

Chart affected - VN50023

259(T)/2018 VIỆT NAM - BỜ BIỂN NAM TRUNG BỘ - QUẢNG NGÃI - DUNG QUẤT - Hệ thống phao.

Nguồn: Tổng công ty Bảo đảm an toàn hàng hải miền Bắc, Thông báo số 380(T)/2018/TBHH-TCTBĐATHH MB

Phao luồng, *Fl.G.3s*, ở vị trí 15°24.27'N, 108°47.56'E tạm ngừng hoạt động.

Phao luồng, *Fl.G.3s*, ở vị trí 15°23.90'N, 108°47.57'E tạm ngừng hoạt động.

Phao an toàn hướng Đông, *Fl.G.3s*, ở vị trí 15°23.73'N, 108°47.44'E tạm ngừng hoạt động.

(Tất cả các vị trí được tham chiếu theo hệ tọa độ WGS84)

Hải đồ ảnh hưởng - VN50023