

184(T)/2017 VIET NAM - NORTH CENTRAL COAST - QUANG BINH - CUA GIANH - Buoyages.

Source: Viet Nam Maritime Safety - North Notice No.252/TBHH-TCTBĐATHH MB

Chart affected - VN50017 (Edition number 3, Edition date Jul 19th, 2017)

Lateral buoy, *Mo(A)6s*, in position 17°43.14'N, 106°30.72'E is temporarily out of service.

Lateral buoy, *Fl.G.3s*, in position 17°42.94'N, 106°30.38'E is temporarily out of service.

Lateral buoy, *Fl.R.3s*, in position 17°42.89'N, 106°30.42'E is temporarily out of service.

Lateral buoy, *Fl.R.3s*, in position 17°42.68'N, 106°30.12'E is temporarily out of service.

Isolated danger buoy, *Fl(2).5s*, in position 17°43.48'N, 106°31.16'E is temporarily out of service.

(All positions are referred to WGS84 Datum)

184(T)/2017 VIỆT NAM - BỜ BIỂN BẮC TRUNG BỘ - QUẢNG BÌNH - CỬA GIANH - Hệ thống phao.

Nguồn: Tổng công ty Bảo đảm an toàn hàng hải miền Bắc, Thông báo số 252/TBHH-TCTBĐATHH MB

Hải đồ ảnh hưởng - VN50017 (Phiên bản 3, ngày 19 tháng 7 năm 2017)

Phao luồng, *Mo(A)6s*, ở vị trí 17°43.14'N, 106°30.72'E tạm ngừng hoạt động.

Phao luồng, *Fl.G.3s*, ở vị trí 17°42.94'N, 106°30.38'E tạm ngừng hoạt động.

Phao luồng, *Fl.R.3s*, ở vị trí 17°42.89'N, 106°30.42'E tạm ngừng hoạt động.

Phao luồng, *Fl.R.3s*, ở vị trí 17°42.68'N, 106°30.12'E tạm ngừng hoạt động.

Phao độc lập nguy hiểm, *Fl(2).5s*, ở vị trí 17°43.48'N, 106°31.16'E tạm ngừng hoạt động.

(Tất cả các vị trí được tham chiếu theo hệ tọa độ WGS84)