

229(T)/2019 VIET NAM - NORTH CENTRAL COAST - THANH HOA - ND NGHI SON - Buoyage.

Source: Viet Nam Maritime Safety - North, Notice No.303(T)/2019/TBHH-TCTBĐATHHMB

The lateral buoy, *Fl.G.3s*, in position 19°18.59'N, 105°48.98'E is temporarily out of service.

The lateral buoy, *Fl.R.3s*, in position 19°18.55'N, 105°48.95'E is temporarily out of service.

The lateral buoy, *Fl.G.3s*, in position 19°18.68'N, 105°48.84'E is temporarily out of service.

The lateral buoy, *Fl.R.3s*, in position 19°18.61'N, 105°48.81'E is temporarily out of service.

The lateral buoy, *Fl.R.3s*, in position 19°18.65'N, 105°48.69'E is temporarily out of service.

(All positions are referred to WGS84 Datum)

Chart affected - VN50012

229(T)/2019 VIỆT NAM - BỜ BIỂN BẮC TRUNG BỘ - THANH HÓA - ND NGHI SƠN - Hệ Thống Phao.

Nguồn: Tổng công ty Bảo đảm an toàn hàng hải miền Bắc, Thông báo số 303(T)/2019/TBHH-TCTBĐATHHMB

Phao luồng, *Fl.G.3s*, ở vị trí 19°18.59'N, 105°48.98'E tạm ngừng hoạt động.

Phao luồng, *Fl.R.3s*, ở vị trí 19°18.55'N, 105°48.95'E tạm ngừng hoạt động.

Phao luồng, *Fl.G.3s*, ở vị trí 19°18.68'N, 105°48.84'E tạm ngừng hoạt động.

Phao luồng, *Fl.R.3s*, ở vị trí 19°18.61'N, 105°48.81'E tạm ngừng hoạt động.

Phao luồng, *Fl.R.3s*, ở vị trí 19°18.65'N, 105°48.69'E tạm ngừng hoạt động.

(Tất cả các vị trí được tham chiếu theo hệ tọa độ WGS84)

Hải đồ ảnh hưởng - VN50012