

204(T)/2017 VIET NAM - NORTH CENTRAL COAST - THANH HOA - LE MON - Buoyage.

Source: Viet Nam Maritime Safety - North Notice No. 287/TBHH-TCTBĐATHH MB

Chart affected - VN40011 (Edition number 1, Edition date April 16th, 2015)

The following buoys are temporarily out of service:

<i>Designation</i>	<i>Type</i>	<i>Position</i>	
LM0	Safe water	19°46.77'N	105°57.85'E
LM9	Starboard hand	19°46.58'N	105°54.25'E
LM9B	Isolated Danger	19°46.44'N	105°53.83'E
LM10	Port hand	19°46.25'N	105°52.87'E
LM11	Starboard hand	19°46.98'N	105°50.59'E
LM12	Port hand	19°46.16'N	105°52.15'E
LM13	Starboard hand	19°47.30'N	105°50.01'E
LM14	Port hand	19°46.19'N	105°51.52'E
LM16	Port hand	19°46.47'N	105°50.96'E

(All positions are referred to WGS84 Datum)

204(T)/2017 VIỆT NAM - BỜ BIỂN BẮC TRUNG BỘ - THANH HÓA - LỆ MÔN - Phao.

Nguồn: Tổng công ty Bảo đảm an toàn hàng hải miền Bắc, Thông báo số 287/TBHH-TCTBĐATHH MB

Hải đồ ảnh hưởng - VN40011 (Phiên bản 1, ngày 16 tháng 4 năm 2015)

Các phao báo hiệu sau đây đang tạm thời ngừng hoạt động:

<i>Tên</i>	<i>Loại</i>	<i>Đặc tính</i>	<i>Vị trí</i>
LM0	Phao vùng nước an toàn	19°46.77'N	105°57.85'E
LM9	Phao phải luồng	19°46.58'N	105°54.25'E
LM9B	Phao nguy hiểm độc lập	19°46.44'N	105°53.83'E
LM10	Phao trái luồng	19°46.25'N	105°52.87'E
LM11	Phao phải luồng	19°46.98'N	105°50.59'E
LM12	Phao trái luồng	19°46.16'N	105°52.15'E
LM13	Phao phải luồng	19°47.30'N	105°50.01'E
LM14	Phao trái luồng	19°46.19'N	105°51.52'E
LM16	Phao trái luồng	19°46.47'N	105°50.96'E

(Tất cả các vị trí được tham chiếu theo hệ tọa độ WGS84)