

**181(T)/2018 VIET NAM - NORTH CENTRAL COAST - THANH HOA - LE MON - Buoyage.**

Source: Viet Nam Maritime Safety - North, Notice No. 272(T)/2018/TBHH-TCTBĐATHH MB

273(T)/2018/TBHH-TCTBĐATHH MB

274(T)/2018/TBHH-TCTBĐATHH MB

The lateral buoy, in position 19°46.25'N, 105°52.87'E is temporarily out of service.

The lateral buoy, in position 19°46.16'N, 105°52.16'E is temporarily out of service.

The lateral buoy, in position 19°47.30'N, 105°50.01'E is temporarily out of service.

The special buoy, in position 19°46.58'N, 105°54.26'E is temporarily out of service.

The special buoy, in position 19°46.45'N, 105°53.83'E is temporarily out of service.

(All positions are referred to WGS84 Datum)

**Chart affected - VN40011****181(T)/2018 VIỆT NAM - BỜ BIỂN BẮC TRUNG BỘ - THANH HÓA - LỆ MÔN - Phao.**

Nguồn: Tổng công ty Bảo đảm an toàn hàng hải miền Bắc, Thông báo số 272(T)/2018/TBHH-TCTBĐATHH MB

273(T)/2018/TBHH-TCTBĐATHH MB

274(T)/2018/TBHH-TCTBĐATHH MB

Phao luồng, ở vị trí 19°46.25'N, 105°52.87'E tạm ngừng hoạt động.

Phao luồng, ở vị trí 19°46.16'N, 105°52.16'E tạm ngừng hoạt động.

Phao đặc biệt, ở vị trí 19°47.30'N, 105°50.01'E tạm ngừng hoạt động.

Phao đặc biệt, ở vị trí 19°46.58'N, 105°54.26'E tạm ngừng hoạt động.

Phao đặc biệt, ở vị trí 19°46.45'N, 105°53.83'E tạm ngừng hoạt động.

(Tất cả các vị trí được tham chiếu theo hệ tọa độ WGS84)

**Hải đồ ảnh hưởng - VN40011**