

**254(T)/2019 VIET NAM - SOUTH EAST COAST - HO CHI MINH - Obstructions.**

Source: Viet Nam Maritime Safety - South, Notice No. 241/TBHH-TCTBĐATHHMN

A Obstruction exists in position 10°32.64'N, 106°51.00'E

A Obstruction exists in position 10°32.72'N, 106°50.94'E

A Obstruction exists in position 10°32.65'N, 106°50.97'E

A Obstruction exists in position 10°32.65'N, 106°50.97'E

A Obstruction exists in position 10°32.74'N, 106°51.01'E

A Obstruction exists in position 10°32.72'N, 106°51.00'E

(All positions are referred to WGS84 Datum)

**Chart affected - VN50033**

**254(T)/2019 VIỆT NAM - BỜ BIỂN ĐÔNG NAM BỘ - HỒ CHÍ MINH - Chướng ngại vật.**

Nguồn: Tổng công ty Bảo đảm an toàn hàng hải miền Nam, Thông báo số 241/TBHH-TCTBĐATHHMN

Chướng ngại vật được xác định tại vị trí 10°32.64'N, 106°51.00'E

Chướng ngại vật được xác định tại vị trí 10°32.72'N, 106°50.94'E

Chướng ngại vật được xác định tại vị trí 10°32.65'N, 106°50.97'E

Chướng ngại vật được xác định tại vị trí 10°32.65'N, 106°50.97'E

Chướng ngại vật được xác định tại vị trí 10°32.74'N, 106°51.01'E

Chướng ngại vật được xác định tại vị trí 10°32.72'N, 106°51.00'E

(Tất cả các vị trí được tham chiếu theo hệ tọa độ WGS84)

**Hải đồ ảnh hưởng - VN50033**