

216(T)/2020 VIET NAM - NORTH EAST COAST - HAI PHONG - Buoyage.

Source: Viet Nam Maritime Safety - North, Notice No. 430(T)/2020/TBHH-TCTBĐATHHMB
433(T)/2020/TBHH-TCTBĐATHHMB

1. The lateral buoy, *Fl.G.3s*, has been temporarily removed from the position 20°48.95'N, 106°50.49'E to 20°48.97'N, 106°50.41'E
2. The lateral buoy, *Fl.R.3s*, has been temporarily removed from the position 20°49.07'N, 106°53.59'E to 20°49.02'N, 106°53.70'E

(All positions are referred to WGS84 Datum)

Chart affected - VN50008

216(T)/2020 VIỆT NAM - BỜ BIỂN ĐÔNG BẮC BỘ - HẢI PHÒNG - Hệ thống phao.

Nguồn: Tổng công ty Bảo đảm an toàn hàng hải miền Bắc, Thông báo số 430(T)/2020/TBHH-TCTBĐATHHMB
433(T)/2020/TBHH-TCTBĐATHHMB

1. Phao luồng, *Fl.G.3s*, được di chuyển tạm thời từ vị trí 20°48.95'N, 106°50.49'E đến 20°48.97'N, 106°50.41'E.
2. Phao luồng, *Fl.R.3s*, được di chuyển tạm thời từ vị trí 20°49.07'N, 106°53.59'E đến 20°49.02'N, 106°53.70'E.

(Tất cả các vị trí được tham chiếu theo hệ tọa độ WGS84)

Hải đồ ảnh hưởng - VN50008